



MA11199 Fitment Verification Process

1. Verify that the bottom of your machine is flat and the tube frame is accessible.
 - a. If there are any protrusions on your skid plate between the seat and the wheels, then the MA11199 is not the appropriate mount for your machine.
 - b. If the skid plate is metal and welded on, you will have to drill through it to mount the Ubolts over the tube frame.
2. Verify that your tube frame narrows between the seat and the wheels. The MA11199 Mount Plate attaches over this narrowing location.

